## 006e3, SmartPlus-e and Hot-Link Plus-e Conversion Chart

Old Model #	Connection	New Model #	Union Fitting Set		T
Old Model #	Connection	14CW WIOGCI #	Required		
00 Standard Mode	ls		- Required		
003-BC4	1/2" sweat		UFS-050S	1/2" sweat	
003-B4	3/4" sweat		UFS-075S	3/4" sweat	
003-BC4-1IFC	1/2" sweat		UFS-050S	1/2" sweat	In-line check valve required
003-BC4-IFC	3/4" sweat		UFS-075S	3/4" sweat	In-line check valve required
003-ST4	3/4" NPT		UFS-075T	3/4" NPT	III III onesk varve required
003-SC4-1	Union	006e3	Various	5, 1 111 1	
003-SC4-IFC	Union	VM1212-DY1-UP2A00	Various		
003 301 11 0	- Cilion	VIVIIZIZ DII OI ZAGO	Various		<u> </u>
006-BC4	1/2" sweat		UFS-050S	1/2" sweat	
006-B4	3/4" sweat		UFS-075S	3/4" sweat	
006-BC7-1IFC	1/2" sweat, IFC		UFS-050S	1/2" sweat	In-line check valve required
006-BC7-IFC	3/4" sweat, IFC		UFS-075S	3/4" sweat	In-line check valve required
006-ST4	3/4" NPT		UFS-075T	3/4" NPT	III line check valve required
006-SC4-1	Union		Various	5/ <del>-</del> 101 1	
006-SC7-IFC	Union		Various		1
000-3C7-II C			various		1
00 - PNP with Line	Cord Only				
003-BC4-4PNP	1/2" sweat		UFS-050S	1/2" sweat	+
003-BC4-4PNP	3/4" sweat		UFS-075S	3/4" sweat	
003-BC4-7PNP	1/2" sweat, IFC		UFS-050S	1/2" sweat	In-line check valve required
003-BC4-7PNP	3/4" sweat, IFC		UFS-075S	3/4" sweat	In-line check valve required
006-BC4-2PNP	1/2" sweat, IFC		UFS-050S	1/2" sweat	in-line check valve required
006-BC4-2PNP	3/4" sweat	000-210-44-14-14		3/4" sweat	
006-B4-1PNP	•	006e3LC with line cord	UFS-050S	1/2" sweat	In line about value verviued
	1/2" sweat, IFC	VM1212-DY1-UP2A01			In-line check valve required
006-BC7-2PNP	3/4" sweat, IFC		UFS-075S	3/4" sweat	In-line check valve required
003-ST4-1PNP	3/4" NPT	-	UFS-075T	3/4" NPT	
003-SC4-2PNP	Union		Various	3/4 141 1	
006-ST4-1PNP	3/4" NPT		UFS-075T	3/4" NPT	
006-SC4-2PNP	Union		Various	3/4 141 1	
000 304 21 141	Onion		various		
SmartPlus				1	
003-IQBC4	1/2" sweat		UFS-050S	1/2" sweat	
003-IQB4	3/4" sweat	SmartPlus-e	UFS-075S	3/4" sweat	
003-IQBC4-1IFC	1/2" sweat, IFC	SPe-1	UFS-050S	1/2" sweat	In-line check valve required
003-IQBC4-IFC	3/4" sweat, IFC	31 6-1	UFS-075S	3/4" sweat	In-line check valve required
003 10201 11 0	3, 1 3, 2, 11 6	Includes:	013 0733	37 1 300000	III iiie eneek varve required
006-IQBC4	1/2" sweat	006e3LC	UFS-050S	1/2" sweat	1
006-IQB4	3/4" sweat	SmartPlug	UFS-075S	3/4" sweat	<u> </u>
006-IQBC7-1IFC	1/2" sweat, IFC	Jiliai triug	UFS-050S	1/2" sweat	In-line check valve required
006-IQBC7-IFC	3/4" sweat, IFC		UFS-075S	3/4" sweat	In-line check valve required
006-IQST4	3/4" NPT		UFS-075T	3/4" NPT	III line check valve required
000 10314	3/ <del>-</del> 10 1		013 0731	3/ <del>-</del> 101 1	
Hot-Link-Plus		Hot-Link Plus-e			
HLP-2		HLPe-1	Included		3/4 male x 3/4" female NPT
IILF -Z	+	ntre-1	included	+	5,4 maie x 5,4 Teillale NFT
		luchi de e	<u> </u>		+
-		Includes:	<u> </u>		+
	+	006e3LC	<u> </u>	+	+
		SmartPlug Hoses & Fittings			+
		_			+
		Hot-Link Valve			